

Additional Funding Request

Site: NY023	WO# 11086 CSS # 27674
Description of Repairs	Remove 100-Watt Mercury Halide Lamp and ballast from existing fixtures and retro fit with two new 54 Watt 5000k LED lamps. Lift is need due to height.
Diagnosis: Initial Work Order CSS# 27674	Repair/replace two light fixtures in the overhang outside the main entrance to building #200
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	12. hrs @ \$125.00, includes 4 hours of diagnostic time= \$1500.00
Additional Material Cost to Perform Repairs	\$170.00
Total Cost of Repair	\$1670.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
11/25/2020	1222

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024

