

Additional Funding Request

Site: NY023	WO# 6895 CSS # 27689
Description of Repairs	The temperature control switch for this PTAC unit is missing. This switch needs to be replaced.
Diagnosis: Initial Work Order CSS# 27689	Asset#9433, fan control switch isn't working and temp control switch is missing.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	2.5 hrs @ \$85.00= \$212.50
Additional Material Cost to Perform Repairs	\$111.60
Total Cost of Repair	\$324.10

WORK ORDER ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

2

Routine

Company Name:	ISG	Facility ID:	NY023
Contractor POC:			
Telephone No:		Building/Location; (e.g., Classroom/Room #)	BUILDING 206/ROOM 103
E-Mail Address:			
Assigned Technician(s):	Deen Rowe		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Asset#9433, fan control switch isn't working and temp control switch is missing. The temperature control switch for this PTAC unit is missing. This switch needs to be replaced.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$85.00	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic	0.5		\$85.00	\$42.50
Labor	2		\$85.00	\$170.00
Temperature Control Switch	1	\$111.60		\$111.60
SUB-TOTAL COSTS:				
	Materials Total		Labor	\$212.50
		TOTAL		\$324.10

Heating/Cooling Control w/ 26" Capillary

SKU

C17-100

Brand

Ranco

Rating



\$85.16 each



ADD TO CART

In Stock

Get 17 **Mon, Nov 30**

More Available [Inventory Details](#) ▾



Fast Track

Order by **5PM**, receive by **Mon**

Free Shipping

Easy Returns