

Additional Funding Request

Site: NY023	WO# 6897 CSS # 27691 Additional Repair Needed
Description of Repairs	. It is not calibrated. The thermostat needs to be replaced in order for the unit to allow heat through the coil.
Diagnosis: Initial Work Order CSS# 27691	ASSET #190917-192 temperature control switch (thermostat) is not working properly
Explanation of Additional Costs for Repairs	upon completion of installation of t stat, found bad control valve material cost 58.00 Labor to install 2.5 hours @85.00=212.50
Additional Labor Cost to Perform Repairs	3.0 hrs @ \$85.00= \$255.00 Additional FR 212.50
Additional Material Cost to Perform Repairs	\$111.60 Additional Material Cost 58.00
Total Cost of Repair	\$366.60 Additinoal FR request 270.50 for increase in approved
Total Cost with additional FR	\$907.50

[Home](#) > [Heating Supplies](#) > [Zone Valves & Controls](#) > [Erie Zone Valves](#) > [Actuators](#)



[Add to List](#)

120V Normally Closed PopTop Series Actuator w/ 96" Leads

Erie

SKU
AG13B060

Brand
Erie

Rating
★★★★★ (1)



\$53.56 each

✓ **In Stock**

Get 8 **Fri, Apr 16**

More Available [Inventory Details](#) ▾

ADD TO CART

FastTrack Order by **5PM**, receive by **Friday**

Free Shipping

On orders over \$99

Easy Returns

No restocking fee for 90 days



CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023- Building 206

Date of Visit: 4/12/21

Location Address: Ft. Totten

Contractor Personnel on Site:

Deen Rowe

Work Performed: g Replaced thermostat on PTAC unit.

Service Calls – PO/CSS# 27691

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deenavughn Rowe

Date: 4/12/21

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Corrado AFOS

Date: 4/13/21

Signed: [Signature]

Email: Louis.A.Corrado@TR. @MAIL.MI /

PIA CKT #21

COOLER

WARMER



TEMPERATURE

III
HI
III
MED
III
LOW
OFF



FAN SPEED

