

Additional Funding Request

Site: NY023	WO# 11121 CSS # 28078
Description of Repairs	Remove and replace lighting fixture B123 small arms room. Lead time is 6-8 weeks
Diagnosis: Initial Work Order	Removal of fluorescent lamps and ballast for three fixtures, replace with direct wire LED lamps with new occupancy sensor switch and stained acrylic lenses.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hrs @ \$125.00= \$1000.00 plus 2 hours of diagnostic @125.00hr Total 1250.00
Additional Material Cost to Perform Repairs	465.00
Total Cost of Repair	\$1715.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
1/3/2021	1230

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024

				Project
Description	Qty	Rate	Total	
NY0023 B200 RM1023 WO2-11121 CSS28078. Removal off fluorescent lamps and ballast from three fixtures, re wiring these fixtures for the installation of direct wire LED replacement lamps and the removal & replacement of the occupancy sensor switch as well as the stained acrylic lenses from the three fixtures. Electrical & Lighting material for the above lighting fixtures and occupancy sensors. Diagnostics fee for above repair.	8	125.00	1,000.00	
		465.00	465.00	
	2	125.00	250.00	
				Subtotal \$1,715.00
				Sales Tax (8.875%) \$0.00
				Total \$1,715.00