

Additional Funding Request

Site: NY023	WO# 11473 CSS # 28280
Description of Repairs	Remove and install new GE 225 AMP 480 Volt Circuit Breaker for Power Panel 15 located in Room 123.
Diagnosis: Initial Work Order CSS# 28280	Repair breaker in B121. Controls panel in B123 that cannot re-set
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hrs @ \$125.00= \$100.00 plus 2 hours of diagnostic @125.00hr Total 1250.00
Additional Material Cost to Perform Repairs	GE 225 Amp Breaker – 775.00
Total Cost of Repair	\$2025.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
12/31/2020	1228

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024

				Project
Description	Qty	Rate	Total	
CSS 28280 Removal and installation of new GE 225 Amp 480 Volt Circuit Breaker for Power Panel 15 located in building 123. This panel controls the air handlers, overhead doors, overhead crane and pump room. The Circuit Breaker was found to be defective and needs to be replaced with a new circuit breaker at the main 800 Amp service switch gear in the Electrical Closet of building 121. New Circuit Breaker for above repair. Diagnostics Fee for above needed repair.	8	125.00	1,000.00	
	1	775.00	775.00	
	2	125.00	250.00	
				Subtotal \$2,025.00
				Sales Tax (8.875%) \$0.00
				Total \$2,025.00