

Additional Funding Request

| | |
|--|--|
| Site: NY023 | WO# 11477 CSS # 28295 |
| Description of Repairs | Remove and replace lighting fixture B123 small arms room. Lead time is 6-8 weeks |
| Diagnosis: Initial Work Order CSS# 28295 | Repair four ft ceiling light fixture in small arms room in AMSA 12. One of two lights out in room. |
| Explanation of Additional Costs for Repairs | |
| Additional Labor Cost to Perform Repairs | 8 hrs @ \$125.00= \$100.00 plus 2 hours of diagnostic @125.00hr Total 1250.00 |
| Additional Material Cost to Perform Repairs | 2x4 Lighting Fixture 770.00 |
| Total Cost of Repair | \$2020.00 |
| | |
| | |

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

| Date | Estimate # |
|------------|------------|
| 12/31/2020 | 1229 |

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024