

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 12532 CSS # 29959</b>
Description of Repairs	Exit Button on single person gate, replaced existing exit button with new. Tested and operating properly. There was one onsite and no material cost.
Diagnosis: Initial Work Order	Repair exit button on single person gate at the outside back of building #200
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	Locurrent Base Service call 600.00
Additional Material Cost to Perform Repairs	0.00
Total Cost of Repair	\$600.00

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PT. Totten, NY  
JND033

Date of Visit: April 16, 2021

Contractor Personnel on Site:

1. Nicholas LoRusso
2. \_\_\_\_\_
3. \_\_\_\_\_
4. CS5# 29959
5. WO# 12532
6. \_\_\_\_\_

#### Service Calls – Service Call Number and Description

1. Exit Button on single person Gate located
2. outside of Bldg. 200 - Replaced existing
3. Exit Button with New. 100% operational.

---

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Nicholas LoRusso Date: 4/16/2021

Signed: Nicholas LoRusso

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: No personnel available at the time of completion.

E-Mail: Can confirm with Mr. Louis Corbo. 1 (917) 405-7165

PUSH  
TO  
EXIT

KANTECH

