

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 12852 CSS # 30207</b>
Description of Repairs	Replace approx. 10ft of 3" copper steam pipe and re-insulate. Check system for proper operation
Diagnosis: Initial Work Order	Diagnose and repair approximately 8 feet of steam pipe leaking in basement of building # 128
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	6 Hrs @ 280.00 per hour = \$1680.00
Additional Material Cost to Perform Repairs	375.00
Total Cost of Repair	\$2055.00

# ACAV SERVICES

April 27, 2021



ESTIMATE 042721 CSS30207 WO12852

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY023 BLDG 128</b> <b>REPLACE 10FT OF 3" COPPER</b> <b>STEAM PIPE</b> <b>RE-INSULATE RESTART SYSTEM</b>		
		<b><u>MATERIAL</u></b> <b>10FT 3" COPPER STEAM PIPE</b> <b>FITTINGS, HANGERS AND</b> <b>INSULATION</b>		<b>\$375.00</b>
		<b><u>LABOR</u></b> <b>6 HRS @\$280.00 PER HOUR</b>		<b>\$1680.00</b>
		<b>TOTAL</b>		<b>\$2055.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581