

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 12858 CSS #30293</b>
Description of Repairs	Removal of 16 lamps and 8 Ballast for four fixtures located in RM 1023 , replacement with direct wired LED replacement lamps.
Diagnosis: Initial Work Order	Repair six 4 foot ceiling lights in the 1023 office area of building # 200
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	10 Hrs @ 125.00 per hour = \$1250.00 INCLUDES 2 HOURS OF DIAGNOSTIC
Additional Material Cost to Perform Repairs	\$368.00
Total Cost of Repair	\$1618.00

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

## Estimate

Date	Estimate #
5/15/2021	1231

Name / Address

---

International Support Group  
9050 Pine Blvd., Suite 150  
Pembroke Pines, FL 33024