

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 30574

Maximo Work Order No. 12876

Asset#:

Date Issued: 05/13/2021

Original Description: Repair roof gutters and leaders disconnecting from the roof at the back of building #124

Description of Repairs: Replace 280ft of Aluminum Gutters, Repair or replace hangers, replace damaged 2" Fiber Foam Insulation. Seal Building.

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				700.00		\$700.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
12 Hrs @ \$195.00	\$2340.00	\$700.00		\$3040.00	1.03%	\$3131.20

Please see attached estimate

ACAV SERVICES

May 24, 2021



ESTIMATE 052421 CSS30574

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 118/124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG 124 BLDG 124 (REAR OF BLDG) REPLACE 280 FT OF ALUMINUM GUTTERS REPAIR OR REPLACE HANGERS REPLACE DAMAGED 2" FIBER FOAM INSULATION SEAL BUILDING		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u> 280 FT ALUMINUM GUTTERS CONNECTORS AND HANGERS 8 SHEETS OF 2" FOAM INSULATION		\$700.00
		<u>LABOR</u> 12 HRS @ \$195.00 PER HOUR		\$2340.00
		TOTAL		\$3040.00
				TOTAL \$3040.00