

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 13351 CSS #31032</b>
Description of Repairs	Remove map gate building 124, remove and replace 12ft steel runner, reinstall gate and align. Check for proper operation
Diagnosis: Initial Work Order	Repair mechanical gate at MEP lot. Guide track at bottom of runner is broken in several places and gets caught in driver motor and stops gate from moving
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	7Hrs @ 225.00 per hour = \$1575.00
Additional Material Cost to Perform Repairs	\$225.00
Total Cost of Repair	\$1800.00

# ACAV SERVICES

June 11, 2021



ESTIMATE 061021 CSS31032 WO13351

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p><b>NY023 BLDG 124 MEP GATE</b></p> <p><b>REMOVE MAP GATE BLDG 124</b></p> <p><b>REMOVE AND REPLACE 12FT STEEL RUNNER</b></p> <p><b>REINSTALL GATE AND ALIGN AND CHECK FOR CORRECT OPERATION</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>12 FT CUSTOM FABRICATED STEEL RUNNER</b></p> <p><b>6EA NEW HANGERS</b></p>		\$225.00

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b><u>LABOR</u></b> <b>7 HRS @ \$225.00 PER HOUR</b>		<b>\$1575.00</b>
		<b>TOTAL</b>		<b>\$1800.00</b>

**TOTAL \$1800.00**