

Additional Funding Request

Site: NY023	WO# 13367 CSS #31127
Description of Repairs	Remove and dispose remaining broken shards of glass, and replace pane of broken glass outside B200, to match other existing panes
Diagnosis: Initial Work Order	As per 7/6/2021 meeting AFR for 4ft x 10ft x 1/2" tempered glass and frame
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	Labor to be submitted separately on Over and Above quote
Additional Material Cost to Perform Repairs	\$
Total Cost of Repair	\$1950.00