

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 13989 CSS # 31318</b>
Description of Repairs	Remove and replace new occupancy sensor for the lightning in the RPAC room. Upon Diagnostic had to bypass temporary sensor for temp. lighting
Diagnosis: Initial Work Order	Center group of lights in RPAC ceiling are not getting power, possible short in three-way switch
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	5 hours @ 125.00 includes two (3) hours of diagnostic- Total Labor \$625.00
Additional Material Cost to Perform Repairs	\$ 115.00
Total Cost of Repair	\$740.00

MSL Electric, LLC  
6555 GRAND AVE  
NY 11378

Estimate

Date	Estimate #
7/2/2021	1253

Name / Address
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

Project
NY0023 200 Duane Road Bayside, NY 11359

			Project
Description	Qty	Rate	Total
Remove and replace with new occupancy sensor for the lighting in the RPAC room. WO2-13989 CSS31318	2	125.00	250.00
Electrical & Lighting material for above installation.		115.00	115.00
Diagnostics for above repair. Lighting occupancy sensor in the RPAC room was temporarily bypassed and the lights are now operational.	3	125.00	375.00
		<b>Subtotal</b>	\$740.00
		<b>Sales Tax (8.875%)</b>	\$0.00
		<b>Total</b>	\$740.00