

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 14845 CSS # 32252</b>
Description of Repairs	Replace drive belts, realign and secure trolley motor, adjust door and rollers, perform overall maintenance.
Diagnosis: Initial Work Order	Repair high bay door on the backside of the OMS shop urgent
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hours @ 235.00 Total Labor \$1880.00
Additional Material Cost to Perform Repairs	\$ 555.00
Total Cost of Repair	\$2435.00

## ACAV SERVICES

September 1, 2021



ESTIMATE 090121 CSS32252 WO14845

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG OMS)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p><b>NY023 BLDG 128</b></p> <p><b>REPAIR BROKEN OVERHEAD HIGH BAY DOOR</b></p> <p><b>REPLACE DRIVE BELTS, ALIGN AND SECURE TROLLEY MOTOR ADJUST DOOR PERFORM PM ON ROLLERS AND ENTIRE DOOR</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>NEW DRIVE BELTS, TROLLEY MOTOR BRACKETS AND HARDWARE</b></p> <p><b><u>LABOR</u></b></p> <p><b>8 HRS @\$235.00 PER HOUR</b></p> <p><b>TOTAL</b></p>		
				<b>\$555.00</b>
				<b>\$1880.00</b>
				<b>\$2435.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581