

Additional Funding Request

Site: NY023	WO# 14853 CSS # 32291
Description of Repairs	Replace drive chain and sprocket, align door and adjust rollers, perform overall maintenance.
Diagnosis: Initial Work Order	Repair high bay door in building # 125 inside the MEP lot does not closed all the time urgent
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hours @ 235.00 Total Labor \$1880.00
Additional Material Cost to Perform Repairs	\$ 475.00
Total Cost of Repair	\$2355.00

ACAV SERVICES

August 31, 2021



ESTIMATE 083121 CSS32291 WO14853

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG OMS)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 125</p> <p>REPAIR BROKEN OVERHEAD HIGH BAY DOOR MEP LOT</p> <p>REPLACE DRIVE CHAIN AND SPROCKET, ALIGN DOOR AND ADJUST PERFORM PM ON ROLLERS</p> <p><u>MATERIAL</u></p> <p>NEW DRIVE CHAIN AND SPROCKET</p> <p><u>LABOR</u></p> <p>8 HRS @\$235.00 PER HOUR</p> <p>TOTAL</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581