

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 15584 CSS #33781</b>
Description of Repairs	Repair Boiler #2, Building # 123, needs Hydrostat. Hydrostat model # 3250+.
Diagnosis: Initial Work Order	Replace defective Hydrostat on Boiler #2
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 hours @225.00=\$900.00
Additional Material Cost to Perform Repairs	\$675.00
Total Cost of Repair	\$1575.00

# ACAV SERVICES

December 13, 2021



ESTIMATE 1213212 CSS33781 W015584

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG 123)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY023 BLDG 123</b> <b>REPLACE DEFECTIVE</b> <b>HYDROSTAT ON BOILER #2</b>		
		<b><u>MATERIAL</u></b> <b>HYDROSTAT MODEL #3250</b>		<b>\$675.00</b>
		<b><u>LABOR</u></b> <b>4 HRS @ \$225.00 PER HOUR</b> <b>(2 MEN 2HRS EACH)</b>		<b>\$900.00</b>
		<b>TOTAL</b>		<b>\$1575.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581