

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 15586 CSS #33783</b>
Description of Repairs	Repair / Adjust Automatic Water Feeders in Building #128.
Diagnosis: Initial Work Order	Replace defective auto feeder valve, gaskets and fittings
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hours @225.00=\$1800.00
Additional Material Cost to Perform Repairs	\$475.00
Total Cost of Repair	\$2275.00

# ACAV SERVICES

December 14, 2021



**ESTIMATE 1214212 CSS33783 W015586**

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG 123)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY023 BLDG 128</b> <b>REPLACE DEFECTIVE AUTO FEEDER VALVE</b>		
		<b><u>MATERIAL</u></b> <b>2 1/2" AUTO FEEDER VALVE GASKETS AND FITTINGS</b>		<b>\$475.00</b>
		<b><u>LABOR</u></b> <b>8 HRS @ \$225.00 PER HOUR</b> <b>(2 MEN 4HRS EACH)</b>		<b>\$1800.00</b>
		<b>TOTAL</b>		<b>\$2275.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581