

Additional Funding Request

Site: NY023	WO# 16859 CSS #35252
Description of Repairs	<p>Remove an install one new 1x4 light fixture in the hallway. Remove and install two new wall mounted occupancy sensors at end of the hallway.</p> <p>LIGHT FIXTURE IS LED TYPE AND WILL HAVE SIX WEEK LEAD TIME ON MATERIAL ETA.</p>
Diagnosis: Initial Work Order	Repair hallway lights in building #118
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	10 total man hours @ 125.00 hr = \$1250.00 INCLUDING TWO HOURS OF DIAGNOSTIC INCURRED
Additional Material Cost to Perform Repairs	\$709.00
Total Cost of Repair	\$1959.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
4/4/2022	1277

Name / Address	Project
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024	NY0023 Ft. Totten 118 Duane Road Bayside, NY 11359

CSS	Work Order	Terms
35252		

Item	Description	Qty	Rate	Total
Service	Removal and installation of one new 1X4 light fixture in the hallway and the removal and installation of two new wall mounted occupancy sensors at each end of the hallway. Lighting fixture is the LED type and requires a 6 week lead time from date of order.	8	125.00	1,000.00
16 Electrical & Li... Service	Electrical & Lighting material for above repair. Diagnostics fee for above repair.	2	709.00 125.00	709.00 250.00
		Subtotal \$1,959.00		
		Sales Tax (8.875%) \$0.00		
		Total \$1,959.00		