

Additional Funding Request

Site: NY058	WO# 19217 CSS # 89627
Description of Repairs	Contractor will need to fabricate and install five (5) keyed locks to secure the automatic control panels
Diagnosis: Initial Work Order	Install five (5) locks on Five (5) different gate motor covers, must have same key.
Explanation of Additional Costs for Repairs	
Additional Labor Costs to Perform Repairs	X2 men <u>5 hours each @ 10 total hours @215.00</u> = \$2150.00
Additional Material Cost to Perform Repairs	315.00
Total Cost of Repair	\$2465.00

ACAV SERVICES

September 8, 2022



ESTIMATE 090822 CSS89627 WO19217

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY23 PARKING AREAS AUTOMATED GATE CONTROLS</p> <p>FABRICATED AND INSTALL 5EA KEYED LOCKS TO SECURE THE AUTOMATIC GATE CONTROL PANELS</p> <p><u>MATERIAL</u></p> <p>5EA MASTER LOCKS (ALL KEYED ALIKE)</p> <p>MISC ANGEL IRON STOCK AND HARDWARE</p> <p>TOTAL MATERIAL</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>LABOR</u> 10 HRS @ \$215.00 PER HOUR (2 MEN 5 HRS EACH)		\$2150.00
		TOTAL		\$2465.00
TOTAL \$2465.00				







PROCEED
SLOWLY

PROCEED
SLOWLY

SI-Hi Security
Manufacturing Company

