

Additional Funding Request

Site: NY023	WO# 19349 CSS #89888
Description of Repairs	CNTR will perform a diagnostic check on 32 FCU. Will remove covers, check electrical functions and manually open all control valves
Diagnosis: Initial Work Order	Diagnose and repair Fan Coil units in Building #206
Explanation of Additional Costs for Repairs	
Additional Labor Costs to Perform Repairs	X1 men 8hours each @ 235.00per hour – 1880.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1880.00

ACAV SERVICES

October 6, 2022



ESTIMATE 100622 CSS89888

Bill To		Ship To		
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO	
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY	
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188	
Phone	954 900 1095			
Payment Due	NET 30	Delivery Date	N/A	
Salesperson	JW	Shipping Method	N/A	
Payment Terms	N/A	Shipping Terms	N/A	

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY23 BLDG 206 RUN DIAGNOSTIC CHECK ON 32 FAN COIL UNITS REMOVE COVERS CHECK ELECTRICAL FUNCTION MANUALLY OPEN CONTROL VALVES <u>LABOR</u> 8 HRS @ \$235.00		\$1880.00
		TOTAL		\$1880.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

