

Additional Funding Request

| | |
|---|--|
| Site: NY023 | WO# 2-19358 CSS # 89959 |
| Description of Repairs | Install new card reader core |
| Diagnosis: Initial Work Order | #2088 Building 123 Repair/Replace Main Door Reader |
| Explanation of Additional Costs for Repairs | |
| Additional Labor Costs to Perform Repairs | X2 men 4hours each @ 85.00 per hour – 680.00 |
| Additional Material Cost to Perform Repairs | 1350.00 |
| Total Cost of Repair | \$2030.00 |
| | |
| | |

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

ISG International Support Group

ESTIMATE # 2088

DATE 09/12/2022

P.O. NUMBER

Ft. Totten, NY Bldg. 123 Reader

| ACTIVITY | QTY | AMOUNT |
|---|-----|----------|
| Services Ft. Totten, NY023 Building 123 Repair/Replace Main Door Reader | 1 | 2,030.00 |

Dear Ms. Dubois:

As per your request, LoCurrent Systems is pleased to provide a quotation to Repair/Replace Main Door Reader at Building 123 at the Ft. Totten, NY023 USARC.

Cost Breakdown:

| | |
|-------------------|------------|
| (1) | |
| Reader..... | \$1,550.00 |
| Core | |
| Rebate..... | (\$200.00) |
| (2) men 8 hours @ | |
| \$85/hr..... | \$680.00 |

| | |
|------------|------------|
| Grand | |
| Total..... | \$2,030.00 |

The cost for the above mentioned work is \$2,030.00

Please note, price is contingent upon completing work while on site for other Tasks.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

| ACTIVITY | QTY | AMOUNT |
|---|-----|--------|
| Thank you so much for thinking of LoCurrent Systems. | | |
| Sincerely, | | |
| Antonietta LoRusso | | |

| | | |
|--|-------|-------------------|
| | TOTAL | \$2,030.00 |
|--|-------|-------------------|

Accepted By

Accepted Date