

Additional Funding Request

Site: NY023	WO# 2-19360 CSS # 89963
Description of Repairs	Further diagnostic quote to determine repair needed at POV Gate Building 200 Card Reader System
Diagnosis: Initial Work Order	Repair CAC readers at main gate
Explanation of Additional Costs for Repairs	
Additional Labor Costs to Perform Repairs	X2 men 8hours each @ 85.00 per hour – 1360.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1360.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS
ISG International Support Group

ESTIMATE # 2091
DATE 09/20/2022

P.O. NUMBER
Ft. Totten Bldg 200 CAC&Gate Op

ACTIVITY	QTY		AMOUNT
Services	1	1,360.00	1,360.00
Ft. Totten, NY023 USARC			
Bldg. 200			
Diagnose Card Reader System and			
Gate Operator at Main Gate to			
Building 200 POV Lot			

Dear Ms. Dubois:

As per your request, LoCurrent Systems is pleased to provide a quotation to Diagnose Card Reader System and Gate Operator at Main Gate to Building 200 POV Lot at the Ft. Totten, NY023 USARC.

Cost Breakdown:

(2) men 8 hours @
\$85/hr.....\$1,360.00

The cost for the above mentioned work is \$1,360.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL

\$1,360.00

Accepted By

Accepted Date