

Additional Funding Request

Site: NY023	WO# 19745 CSS # 90419
Description of Repairs	Clean out grease pit in kitchen of Building #200
Diagnosis: Initial Work Order	Clean out building mess hall grease trap
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	2500.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$2500.00

ACAV SERVICES

November 29, 2022



ESTIMATE 112922 CSS90419 WO19745

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 200) (MESS HALL)		
		CLEAN OUT BUILDING MESS HALL GREASE TRAP <u>LABOR</u> 10 HRS @ \$250.00 (2 MEN 5 HRS EA) BYPRODUCT IS COOKING GREASE AND WILL BE DISPOSED OF ACCORDINGLY IT IS NOT CONSIDERED A HAZARDOUS MATERIAL		\$2500.00
		TOTAL		\$2500.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

