

Additional Funding Request

Site: NY023-330	WO# 19765 CSS #90605
Description of Repairs	Weld broken railing at rear of building
Diagnosis: Initial Work Order	repair railing building 330B exterior steps
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	X2 men @ 2hrs each @ 235.00= 940.00 Repair Labor
Additional Material Cost to Perform Repairs	
Total Cost of Repair	940.00

ACAV SERVICES

November 4, 2022



ESTIMATE 110422B CSS90605 WO19765

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 330B) REPAIR BROKEN RAILING AT REAR OF BUILDING		
		<u>LABOR</u> 4 HRS @ \$235.00 (WELDER AND HELPER)		\$940.00
		TOTAL		\$940.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

