

Additional Funding Request

Site: NY023-330	WO# 19767 CSS #90615
Description of Repairs	Remove the door and replace a portion of the door frame, rehang the door and adjust for proper operation.
Diagnosis: Initial Work Order	building 330A repair double doors leading into the corridor to B section, and double doors leading into the 151 area
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 hrs @ 225.00= 900.00 Repair Labor
Additional Material Cost to Perform Repairs	
Total Cost of Repair	900.00

ACAV SERVICES

November 4, 2022



ESTIMATE 110422A CSS90615 WO19767

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330B)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 330B) BROKEN DOUBLE DOOR LEADING TO SECTION B REMOVE DOOR AND REPLACE PORTION OF THE FRAME REHANG DOOR AND ADJUST <u>LABOR</u> 4 HRS @ \$225.00		\$900.00
		TOTAL		\$900.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

