

Additional Funding Request

Site: NY023	WO#20197 CSS # 90940
Description of Repairs	10 ea thermostatic right angle radiators valves need to adjusted, 4 ea will need to be replaced.
Diagnosis: Initial Work Order	Building 128 diagnose and repair radiators
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	260.00
Additional Material Cost to Perform Repairs	1000.00
Total Cost of Repair	\$1260.00

ACAV SERVICES

December 10, 2022



ESTIMATE 1210221 CSS90940 WO20197

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 128) RADIATORS NOT WORKING		
		10EA THERMOSTATIC RIGHT ANGLE RADIATORS VALVES NEED TO BE ADJUSTED		
		4EA WILL NEED TO BE REPLACED		
		<u>MATERIAL</u>		
		4EA DANFOSS RA200 THERMOSTATIC RIGHT-ANGLE VALVES (OR SIMILAR) \$65.00 EA		
		<u>LABOR</u>		\$260.00
		4 HRS @ \$250.00		\$1000.00
		TOTAL		\$1260.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581















