

Additional Funding Request

Site: NY023	WO#20198 CSS # 90941
Description of Repairs	Repair leaking steam radiator, remove radiator, replace coupling below floor, drain radiator and replace steam valve and reinstall.
Diagnosis: Initial Work Order	Building 330 repair radiator leak
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	125.00
Additional Material Cost to Perform Repairs	1500.00
Total Cost of Repair	\$1625.00

ACAV SERVICES

December 9, 2022



ESTIMATE 120922 CSS90941 WO20198

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 330) REPAIR LEAKING STEAM RADIATOR REMOVE RADIATOR REPLACE COUPLING BELOW FLOOR DRAIN RADIATOR REPLACE STEAM VALVE REINSTALL RADIATOR		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u> 2EA 1 1/4 GALVANIZED COUPLINGS AND MISC PARTS 1EA STEAM VALVE		\$75.00 \$50.00
		<u>TOTAL MATERIAL</u>		\$125.00
		<u>LABOR</u> 6 HRS @ \$250.00 (2 MEN 3 HRS EA)		\$1500.00
		TOTAL		\$1625.00
TOTAL \$1625.00				

