

Additional Funding Request

Site: NY023	WO#20200 CSS # 90943
Description of Repairs	Repair leaking toilet, replace leaking flush valve
Diagnosis: Initial Work Order	Building 128 Men's bathroom toilet leak
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	225.00
Additional Material Cost to Perform Repairs	1000.00
Total Cost of Repair	\$1225.00

ACAV SERVICES

December 10, 2022



ESTIMATE 121022 CSS90943 WO20200

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 128) 2 ND FLOOR MENS LATRINE REPAIR LEAKING TOILET REPLACE LEAKING FLUSH VALVE REST BOWL <u>MATERIAL</u> 1EA SLOAN FLUSH VALVE <u>LABOR</u> 4 HRS @ \$250.00		\$225.00
				\$1000.00
		TOTAL		\$1225.00
TOTAL				\$1225.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581



