

Additional Funding Request

Site: NY023	WO#20590 CSS # 91214
Description of Repairs	Install security guard on the window in the computer room. Frame out and install.
Diagnosis: Initial Work Order	building 128, room 101, security bars for secure coms room window.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	500.00
Additional Material Cost to Perform Repairs	265.00
Total Cost of Repair	\$765.00

ACAV SERVICES

December 19, 2022



ESTIMATE 121922 CSS91214 WO20590

Bill To		Ship To		
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO	
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY	
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188	
Phone	954 900 1095			
Payment Due	NET 30	Delivery Date	N/A	
Salesperson	JW	Shipping Method	N/A	
Payment Terms	N/A	Shipping Terms	N/A	

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 128) (ROOM 101 COMPUTER ROOM)</p> <p>INSTALL SECURITY GUARD ON WINDOW IN COMPUTER ROOM</p> <p>FRAME OUT AND INSTALL</p> <p><u>MATERIAL</u></p> <p>1EA 3X4 HEAVY DUTY SECURITY SCREEN</p> <p>6FT 1X4 COMMON</p> <p><u>LABOR</u></p> <p>2 HRS @ \$250.00</p> <p>TOTAL</p>		<p>\$265.00</p> <p>\$500.00</p> <p>\$765.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

