

## Additional Funding Request

<b>Site: NY023</b>	<b>WO#20613 CSS # 91437</b>
Description of Repairs	REPAIR BOILER LEAK   REPAIR LEAK IN STEAM TANK REGULATOR FOR HEATING   SYSTEM (LEAKING)
Diagnosis: Initial Work Order	Building 128 fix boiler leak
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1250.00
Additional Material Cost to Perform Repairs	65.00
Total Cost of Repair	\$1315.00

# ACAV SERVICES

January 14, 2023



ESTIMATE 011423 CSS91437 WO20613

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 128)</b></p> <p><b>REPAIR BOILER LEAK</b></p> <p><b>REPAIR LEAK IN STEAM TANK</b></p> <p><b>REGULATOR FOR HEATING</b></p> <p><b>SYSTEM (LEAKING)</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA 11/4" STEEL TO COOPER 1"</b></p> <p><b>FITTING</b></p> <p><b>1EA 1" COOPER COUPLING</b></p>		<b>\$65.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b><u>LABOR</u></b> <b>5 HRS @ \$250.00</b> <b>(INCLUDES 1HR DIAGNOSTIC FEE)</b>		<b>\$1250.00</b>
		<b>TOTAL</b>		<b>\$1315.00</b>



