

Additional Funding Request

Site: NY023	WO#20626 CSS # 91518
Description of Repairs	Repair the leaking radiator, disconnect the cast iron radiator, and remove the defective 1 /14 " steam valve and coupling. Install new coupling and 1ea 1 ¼" steam valve
Diagnosis: Initial Work Order	Building 330A Room 103 repair radiator leak
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1000.00
Additional Material Cost to Perform Repairs	140.00
Total Cost of Repair	\$1140.00

ACAV SERVICES

January 15, 2023



ESTIMATE 011523A CSS91518 W020626

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 330A RM 103)</p> <p>REPAIR LEAKING RADIATOR</p> <p>DISCONNECT CAST IRON</p> <p>RADIATOR REMOVE DEFECTIVE</p> <p>1 1/4" STEAM VALVE AND</p> <p>COUPLING.</p> <p>INSTALL NEW COUPLING AND</p> <p>1EA 1 1/4" STEAM VALVE</p> <p><u>MATERIAL</u></p> <p>1EA 1/1/4" STEAM VALVE AND</p> <p>COUPLING</p>		\$140.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>LABOR</u> 4 HRS @ \$250.00 (2 MEN 2HRS EACH)		\$1000.00
		TOTAL		\$1140.00

\$

TOTAL \$1140.00

