

## Additional Funding Request

|                                             |                                                                                                      |
|---------------------------------------------|------------------------------------------------------------------------------------------------------|
| <b>Site: NY023</b>                          | <b>WO# 21041 CSS # 91646</b>                                                                         |
| Description of Repairs                      | Disconnect the cast iron radiator, remove the defective 1 ¼ steam valve and coupling and install new |
| Diagnosis: Initial Work Order               | Building 330A Room 101 repair radiator leak                                                          |
| Explanation of Additional Costs for Repairs |                                                                                                      |
| Additional Labor Cost to Perform Repairs    | 1000.00                                                                                              |
| Additional Material Cost to Perform Repairs | 140.00                                                                                               |
| Total Cost of Repair                        | \$1140.00                                                                                            |
|                                             |                                                                                                      |
|                                             |                                                                                                      |

# ACAV SERVICES

January 17, 2023



ESTIMATE 011723 CSS91646 WO21041

| Bill To       |                                                       | Ship To         |                                              |
|---------------|-------------------------------------------------------|-----------------|----------------------------------------------|
| Customer      | International Support Group<br>M DUBOIS,              | Recipient       | 99 RSC RD DPW<br>L CORBO                     |
| Customer ID#  | NY023 (BLDG 330A)                                     | Address         | Ernie Pyle USARC<br>BLDG 206<br>Ft Totten NY |
| Address       | 9050 Pines Blvd<br>STE 150<br>Pembroke Pines FL 33024 | Phone           | 718 631 6188                                 |
| Phone         | 954 900 1095                                          |                 |                                              |
| Payment Due   | NET 30                                                | Delivery Date   | N/A                                          |
| Salesperson   | JW                                                    | Shipping Method | N/A                                          |
| Payment Terms | N/A                                                   | Shipping Terms  | N/A                                          |

| Qty. | Item# | Description                                                                                                                                                                                                                                                                                                                                                                                   | Unit Price | Line Total      |
|------|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------------|
|      |       | <p><b>NY23 (BLDG 330A RM 101)</b></p> <p><b>REPAIR LEAKING RADIATOR</b></p> <p><b>DISCONNECT CAST IRON</b></p> <p><b>RADIATOR REMOVE DEFECTIVE</b></p> <p><b>1 1/4" STEAM VALVE AND</b></p> <p><b>COUPLING.</b></p> <p><b>INSTALL NEW COUPLING AND</b></p> <p><b>1EA 1 1/4" STEAM VALVE</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA 1 1/4" STEAM VALVE AND</b></p> <p><b>COUPLING</b></p> |            | <b>\$140.00</b> |

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

| Qty. | Item# | Description                                                                | Unit Price | Line Total       |
|------|-------|----------------------------------------------------------------------------|------------|------------------|
|      |       | <b><u>LABOR</u></b><br><b>4 HRS @ \$250.00</b><br><b>(2 MEN 2HRS EACH)</b> |            | <b>\$1000.00</b> |
|      |       | <b>TOTAL</b>                                                               |            | <b>\$1140.00</b> |

\$

**TOTAL \$1140.00**

