

Additional Funding Request

Site: NY023	WO#21047 CSS # 91700
Description of Repairs	Repair non-working leaking radiator, broken thermostatic valve. Block and reset radiator.
Diagnosis: Initial Work Order	Building 330A repair radiator leak in 151 AO radiator and floor previously repaired this is new
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	500.00
Additional Material Cost to Perform Repairs	195.00
Total Cost of Repair	\$695.00

ACAV SERVICES

January 25, 2023



ESTIMATE 012523 CSS91700 WO21047

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 330A COMMON AREA)</p> <p>REPAIR NON WORKING LEAKING RADIATOR (BROKEN THERMOSTATIC VALVE) BLOCK AND RESET RADIATOR</p> <p><u>MATERIAL</u></p> <p>1EA DANFOOS RA2000 013G 8013 THERMOTIC VALVE</p> <p><u>LABOR</u></p> <p>2 HRS @ \$250.00</p>		\$195.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		TOTAL		\$695.00

\$

TOTAL \$695.00

