

Additional Funding Request

Site: NY023	WO# 21446 CSS #92207
Description of Repairs	Replace the defective cast iron radiator. Disconnect and remove the defective cast iron radiator and install a new 32x36x8 cast iron radiator. Test for proper operation.
Diagnosis: Initial Work Order	Building 330 room 204 replace defective radiator
Explanation of Additional Costs for Repairs	
Additional Labor Costs to Perform Repairs	X2 men @ 3 hours each=1500.00
Additional Material Cost to Perform Repairs	872.00
Total Cost of Repair	\$2372.00

ACAV SERVICES

February 16, 2023



ESTIMATE 021623 CSS92207 WO21446

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 330A RM 204 EAST END OF BUILDING)</p> <p>REPLACE DEFECTIVE CAST IRON RADIATOR</p> <p>DISCONNECT AND REMOVE DEFECTIVE CAST IRON RADIATOR</p> <p>INSTALL NEW 32X36X8 CAST IRON RADIATOR</p> <p>TEST SYSTEM</p> <p><u>MATERIAL</u></p> <p>1EA 32X36X8 CAST IRON RADIATOR</p>		\$872.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>LABOR</u> 6 HRS @ \$250.00 (2 MEN 3HRS EACH)		
				\$1500.00
		TOTAL		\$2372.00
				TOTAL \$2372.00

