

## Additional Funding Request

<b>Site: NY023</b>	<b>WO#21450 CSS # 92237</b>
Description of Repairs	Replace defective door closure. Disconnect, remove, and replace door closure. Adjust and tighten hinges.
Diagnosis: Initial Work Order	Building 200 domestic hot water heater diagnose and repair.it has been disassembled for at least a year
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	500.00
Additional Material Cost to Perform Repairs	190.00
Total Cost of Repair	\$690.00

# ACAV SERVICES

February 23, 2023



ESTIMATE 021723 CSS92237 WO21450

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 206 RM 107 LATRINE)</b></p> <p><b>REPLACE DEFECTIVE DOOR CLOSER</b></p> <p><b>DISCONNECT, REMOVE AND REPLACE DOOR CLOSER</b></p> <p><b>ADJUST AND TIGHTEN HINGES</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA AUTOMATIC DOOR CLOSER</b></p> <p><b><u>LABOR</u></b></p> <p><b>2 HRS @ \$250.00</b></p> <p><b>TOTAL</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581



Door Is Broken