

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 21473CSS # 92405</b>
Description of Repairs	Remove the toilet and reset with a new seal. Replace Fill Spud
Diagnosis: Initial Work Order	Building 206 3rd floor bathroom toilet leak needs repair
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	500.00
Additional Material Cost to Perform Repairs	150.00
Total Cost of Repair	\$650.00

# ACAV SERVICES

March 15, 2023



ESTIMATE 031623 CSS92405 WO21473

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	3 MAR 2023
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<b>NY23 (BLDG 206) 3<sup>RD</sup> FLOOR LATRINE</b> <b>TOILET LEAKING</b> <b>REMOVE TOILET AND RESEAT WITH NEW SEAL</b> <b>REPLACE FILL SPUD</b> <b><u>MATERIAL</u></b> <b>1EA TOILET WAX RING</b> <b>1EA 1 ¼ SPUD</b> <b>TOTAL MATERIAL</b> <b><u>LABOR</u></b> <b>2 HRS @ \$250.00</b> <b>TOTAL</b>		<b>\$150.00</b> <b>\$500.00</b> <b>\$650.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

