

Additional Funding Request

Site: NY023	WO#21482 CSS # 92467
Description of Repairs	Repair Broken lock in Women Restroom, Cut out old knob less lock assemblies and install with new knob less lock assembly
Diagnosis: Initial Work Order	Building 124 Replace women bathroom door lock
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	900.00
Additional Material Cost to Perform Repairs	385.00
Total Cost of Repair	\$1285.00

ACAV SERVICES

March 8, 2023




ESTIMATE 030923 CSS92467 WO21482

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 124)		
		REPAIR BROKEN LOCK IN WOMENS LATRINE		
		CUT OUT OLD KNOP LESS LOCK ASSEMBLIES INSTALL NEW KNOP LESS LOCK ASSEMBLY		
		<u>MATERIAL</u>		
		1 EA ARROW N-AUXILIARY LOCK SET \$385.00 EA		\$385.00
		<u>LABOR</u>		
		4 HRS @ \$225.00 (2 MEN 2HRS)		\$900.00
		TOTAL		\$1285.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581





ARROW