

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 21730 CSS # 92473</b>
Description of Repairs	Remove and Replace 55 ea. 2x4 ceiling tiles that are missing or damaged with Mildew-resistant tiles.
Diagnosis: Initial Work Order	building 330 replace damaged and mismatched ceiling tiles
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1200.00
Additional Material Cost to Perform Repairs	750.00
Total Cost of Repair	\$1950.00



# ACAV SERVICES

March 30, 2023



ESTIMATE 033023 CSS92473 WO21730

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 330A)</b></p> <p><b>REPLACE 55 EA 2X4 CEILING TILE TO REPLACE MISSING AND DAMAGED TILE</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>55 EA Acoustical Ceiling Tiles Iconic Petra Ceiling Tile 2x4 MILDEW RESISTANT</b></p> <p><b>6 BOXES @ \$125.00 PER BOW</b></p> <p><b><u>LABOR</u></b></p> <p><b>8 HRS @ 150.00 PER HR</b></p> <p><b><u>TOTAL</u></b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581