

## Additional Funding Request

<b>Site: NY058</b>	<b>WO# 21786 CSS #93084</b>
Description of Repairs	Remove and rehang the Telecom rack in Rm 204. The existing rack is not fastened properly to any studs to support the weight. Will remove the rack and reinstall it with backer boards for support and properly secure with screws and construction adhesive.
Diagnosis: Initial Work Order	Repair and re hang telecoms rack building 206 rm 204.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1200.00
Additional Material Cost to Perform Repairs	50.00
Total Cost of Repair	\$1250.00

# ACAV SERVICES

April 14, 2023



ESTIMATE 041423 CSS93084 WO21786

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	30 MAR 23
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 206) RM 204</b></p> <p><b>REHANG TELECOM RACK IN RM 204</b></p> <p><b>THE RACK WAS NOT INSTALLED PROPERLY, WHO EVER SECURED THE RACK TO THE WALL (SHEET ROCK) DID NOT FASTEN THE FRAME TO ANY STUDS BEHIND THE SHEETROCK</b></p> <p><b>TWO MEN WILL BE REQUIRED TO REMOVE THE RACK AND TEMPORALLY SUPPORT IT WHILE BACKER BOARDS COULD BE CUT TO SIZE AND THEN</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b>PROPERLY SECURED WITH SCREWS AND CONSTRUCTION ADHESIVE. THIS HAD TO BE ACCOMPLISHED WITH COORDINATION WITH THE IT PERSONNEL</b>		
		<b><u>MATERIAL</u></b>		
		<b>2X8X8 BOARD</b>		<b>\$50.00</b>
		<b>CONSTRUCTION ADHESIVE</b>		
		<b><u>LABOR</u></b>		
		<b>6 HRS @ 200.00 PER HR</b>		<b>\$1200.00</b>
		<b>(2 MEN 3HRS EA)</b>		
		<b>TOTAL</b>		<b>\$1250.00</b>
				<b>TOTAL \$1250.00</b>

