

Additional Funding Request

Site: NY023	WO# 21785 CSS #93086
Description of Repairs	Remove urinals and clean common urinal drain of calcium build-up in lines. Reset urinal and test system
Diagnosis: Initial Work Order	Building 330 Men's basement bathroom all 3-urinals are overflowing and unusable.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	570.00
Additional Material Cost to Perform Repairs	29.00
Total Cost of Repair	\$599.00

ACAV SERVICES

April 21, 2023



ESTIMATE 042123 CSS93086 WO21785

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (330A)		
		BASEMENT MENS LATRINE URINALS 3EA CLOGGED		
		REMOVE URINALS, CLEAN COMMON URINAL DRAIN OF CALCIUM BUILD UP IN LINES		
		RESET URINALS AND TEST SYSTEM		
		<u>MATERIAL</u>		
		3EA 1 1/2 O RINGS		
		2EA 1 1/2 ELBOW		\$29.00
		<u>LABOR</u>		
		3 HRS @ 190.00 PER HR		\$570.00
		TOTAL		\$599.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

