

Additional Funding Request

Site: NY023	CSS # 22990 WO-2-6507
Description of Repairs	Diagnose parking lot back entrance gate in the top lot at the third floor entrance to building #200
Diagnosis: Initial Work Order CSS# 22990	Repair Hy Security motorized gate operator is not functioning properly because of the 6" Knobby Drive Wheel for the Xtreme Drive System is worn down and needs replacement.
Explanation of Additional Costs for Repairs	<ul style="list-style-type: none"> • Mobilization to the site with equipment needed (New Hy Security 6" Knobby Drive Wheel and tools needed to remove the old Drive Wheel and install new Drive Wheel). • Remove and dispose of offsite the existing 6" Knobby Wheel Drive • Supply and install new Hy Security 6" Knobby Wheel Drive for Xtreme Drive system • Test gate operator for proper function • Clean up work area upon completion and demobilize
Additional Labor Cost to Perform Repairs	1 x \$400.00 = \$400.0
Additional Material Cost to Perform Repairs	\$546.50
Total Cost of Repair	\$946.50
Notes:	

12-16-2019

Fort Totten - Bldg 200 Gate Operator Repair Quote by 3rd Floor Entrance

To: International Support Group
Attn: Ms. Michele Dubois (Site Supervisor)
Address: 9050 Pines Blvd., Suite 150, Pembroke Pines, FL 33024
Email: mdubois@internationalsupportgroup.com
Phone: (954) 900-1095

Location: Fort Totten, Bldg 206, Flushing, NY
RE: Service Request # CSS 22990, WO # 2-6507

URGENT ASSESSMENT COST:

- Sent out a project manager to respond to this Urgent Service Request. Our project manager arrived and contacted Mr. Louis Corbo from 99th RSC. After locating the issues, the Hy Security motorized gate operator is not functioning properly because of the 6" Knobby Drive Wheel for the Xtreme Drive System is worn down and needs replacement. Our Project Manager will not be able to take of the repairs under the \$450 limit repair site visit cost. We have included our assessment cost, along with the cost necessary to do the repairs needed.

Emergency Assessment Cost: 3 hours @ \$100 per hour = \$300

TOTAL EMERGENCY ASSESSMENT COST: \$300

Scope of Work:

- Mobilization to the site with equipment needed (New Hy Security 6" Knobby Drive Wheel and tools needed to remove the old Drive Wheel and install new Drive Wheel).
- Remove and dispose of offsite the existing 6" Knobby Wheel Drive
- Supply and install new Hy Security 6" Knobby Wheel Drive for Xtreme Drive system
- Test gate operator for proper function
- Clean up work area upon completion and demobilize



12-16-2019

Fort Totten - Bldg 200 Gate Operator Repair Quote by 3rd Floor Entrance

BREAKDOWN OF COSTS:

ITEM DESCRIPTION	COST
Mobilization of equipment (New Hy Security 6" Knobby Drive Wheel for Xtreme Drive System and tools needed for removal of old and installation of new Drive Wheel)	\$100.00
New Hy Security 6" Knobby Drive Wheel	\$346.50
Demobilization of equipment	\$100.00
Labor Needed: 1 man x 4 hrs x \$100 per hour:	\$400.00
QUOTE TOTAL:	\$946.50

QUOTATION VALID FOR: 30 DAYS FROM QUOTATION DATE

ACCEPTANCE OF QUOTATION:

The above price, conditions and specifications are hereby accepted. You are authorized to do the work as specified. Payment schedule: Cost of all materials up front and balance upon completion of work.

QUOTE ACCEPTANCE:

Client's Printed Name: _____

Client's Acceptance Signature: _____

Date: _____

