

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST **Interior LIGHTING**

SITE AND BLDG #: NY058-104

MECHANIC SIGNATURE: DEEN ROWE

DATE: 10/2/20

LOCATION/RM #: Entire Shoreham Facility

START TIME: 8am

FINISH TIME: 12pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY058-104	10270	190917-320			165-pc Interior Lights 4 Flourescent	
NY058-104	In the	Boiler Room	4		4ft lights	Ballast issue
NY058-104	In the	Men's Bathroom	20		Fluor Lamp	Replace
NY058-104	In the	women's Bathroom	30		fluor bulb	Replace
NY058-104	Mechanical Room	2nd floor	12		4ft lights	Ballast issue
NY058-104	Hall way		2		4ft lights	Replace
NY058-104	Class Room B (226)		2		4ft lights	Replace
NY058-104	2nd floor offices		2		fluor bulb	replace

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Light out
Main Entrance
↓
B.104



* Need A Lft (Maybe Mike the Electrician can fix)



← Needs to be
26w/32w/42w
triple Fluor
Lamp.

* All Lights Are Out In female Bathroom on 2nd Floor

