

## Additional Funding Request

<b>Site: NY058</b>	<b>CSS # 21679 WO-5703</b>
Description of Repairs	<b>Glass Pane Replacement:</b> <ul style="list-style-type: none"> <li>• Measure the exact size window pane needed</li> <li>• Supply and install 3/8" clear tempered, polished on all 4 sides, and glass will have (2) holes for architectural clips (Approx. Glass Size: 40" x 40")</li> <li>• Re-glaze around the new glass.</li> </ul>
Diagnosis: Initial Work Order <b>CSS# 21679</b>	Replace Glass pane that fell off leaving an opening
Explanation of Additional Costs for Repairs	Labor and material to complete call
Additional Labor Cost to Perform Repairs + <b>Incurred cost of \$400.00</b>	4x\$100.00=\$400.00 Incurred cost =\$400.00 <b>Total Labor Cost of \$800.00</b>
Additional Material Cost to Perform Repairs	\$ 185.00
Total Cost of Repair	\$985.00



10-11-2019

---

**Urgent Work Order Glass Pane Repair Quote - USARC Shoreham, NY**

To: International Support Group  
Attn: Mr. Jamie Merchant (Site Supervisor)  
Address: 9050 Pines Blvd., Suite 150, Pembroke Pines, FL 33024  
Email: jmerchant@internationalsupportgroup.com

Location: USARC, 200 Route 25A, Shoreham, NY

**Scope of Work:**

\*\*\* Please note this quote is based on paying normal wages \*\*\*

**EMERGENCY ASSESSMENT COST:**

- Sent out a project manager to respond to this Urgent work order. Our project manager arrived and contacted Mr. Bob Bennet from 99th RSC. After locating the broken window pane, we will need to get a new pane made to exact size. Our Project Manager will not be able to take of the repairs under the \$450 limit repair site visit cost. We have included our assessment cost, along with the cost necessary to do the repairs needed.

Emergency Assessment Cost: 4 hours @ \$100 per hour = \$400

**TOTAL EMERGENCY ASSESMENT COST: \$400**



**Urgent Work Order Glass Pane Repair Quote - USARC Shoreham, NY**

**Glass Pane Replacement:**

- Measure the exact size window pane needed
- Supply and install 3/8" clear tempered, polished on all 4 sides, and glass will have (2) holes for architectural clips (Approx. Glass Size: 40" x 40")
- Re-glaze around the new glass.

Fix Cost: 4 hours @ \$100 per hour = \$400  
Window Cost: \$185.00

**TOTAL GLASS REPLACEMENT COST: \$585.00**

QUOTATION VALID FOR: 30 DAYS FROM QUOTATION DATE

**ACCEPTANCE OF QUOTATION:**

The above price, conditions and specifications are hereby accepted. You are authorized to do the work as specified. Payment schedule: Cost of all materials up front and balance upon completion of work.

**QUOTE ACCEPTANCE:**

Client's Printed Name: \_\_\_\_\_

Client's Acceptance Signature: \_\_\_\_\_

Date: \_\_\_\_\_