

## Additional Funding Request

| <b>Site: NY058</b>                                 | <b>WO# 9728    CSS # 25967    Asset# NA</b>   |
|--|---|
| Description of Repairs                             | Bypass inoperable BMS System, inspect every controller and valve manually to determine all problems and correct temperature settings. |
| Diagnosis: Initial Work Order<br><b>CSS# 25967</b> | AFOS reports temps of 78-80 in common areas of the training building  |
| Explanation of Additional Costs for Repairs        | Labor intense due to process  |
| Additional Labor Cost to Perform Repairs           | 10 hours @ 220.00 per hour  |
| Additional Material Cost to Perform Repairs        |   |
| Total Cost of Repair                               | <b>\$2200.00</b>  |
|  |   |
|  |   |

# ACAV SERVICES

July 27, 2020



ESTIMATE 072720 CSS WO

| Bill To              |   | Ship To                |  |
|----------------------|---|------------------------|--|
| Customer             | International Support Group<br>J Merchant,            | Recipient              | 99 RSC DPW<br>R Linn                         |
| Customer ID#         | NY058 (Shoreham USARC)                                | Address                | Ernie Pyle USARC<br>BLDG 200<br>Ft Totten NY |
| Address              | 9050 Pines Blvd<br>STE 150<br>Pembroke Pines FL 33024 | Phone                  | 718 631 6188                                 |
| Phone                | 718 790 3562  |                        |  |
| <b>Payment Due</b>   | NET 30  | <b>Delivery Date</b>   | July 31, 2020                                |
| <b>Salesperson</b>   | JW  | <b>Shipping Method</b> | N/A  |
| <b>Payment Terms</b> | CC  | <b>Shipping Terms</b>  | N/A  |

| Qty. | Item# | Description  | Unit Price | Line Total |
|------|-------|--|------------|------------|
| 1    | 1     | <b>NY058 Shoreham USARC (MAIN BLDG)</b><br><br><b>TROUBLE SHOOT ENTIRE AC SYSTEM AND RESET/REPAIR</b><br><br><b>NOTE</b><br><br><b>THE BMS SYSTEM IN THIS BUILDING IS NOT OPERATING. THE TECHNICIAN WILL NEED TO INSPECT EVERY CONTROLLER AND VALVE MANUALLY TO DETERMINE THE PROBLEM AND CORRECT TEMP SETTINGS. THIS IS A LABOR INTENSE PROCESS THAT CAN ONLY BE RESOLVED BY A VISUALLY INSPECTION OF ALL THE COMPONENTS.</b> |            |            |

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

| Qty. | Item# | Description                               | Unit Price   | Line Total       |
|------|-------|---|--------------|------------------|
|      |       | <b>Labor 10 hours @ \$220.00 per hour</b> |              | <b>\$2200.00</b> |
|      |       | <b>TOTAL</b>                              |              | <b>\$2200.00</b> |
|      |       |   | <b>TOTAL</b> | <b>\$2200.00</b> |