

Additional Funding Request

Site: NY058	WO# 29894 CSS # 12528
Description of Repairs	Facility seasonal change over requested
Diagnosis: Initial Work Order	Seasonal AC Change over. Diagnose and reset and override all controller due to defective BMS system
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 Hours @ 285.00= \$2280.00
Additional Material Cost to Perform Repairs	\$0.00
Total Cost of Repair	\$2280.00

ACAV SERVICES

April 6, 2021



ESTIMATE 040521 CSS29894 WO12528

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BUILDING SEASONAL AC CHANEOVER DIAGNOSE AND RESET/OVER RIDE ALL CONTROLLERS (NOT WORK BECAUSE OF DEFECTIVE BMS SYSTEM) LABOR HVAC CONTROL SPECIALIST 8 HRS @ \$285.00 PER HR THIS ESTIMATE IS BASED ON THE ASSUMPTION THAT NO PARTS WILL NEED TO BE REPLACED. IF ANY DEFECTIVE PARTS ARE DISCOVERED WILL ADVISE ISG TOTAL		\$2280.00
				\$2280.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581