

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 12854 CSS # 30217</b>
Description of Repairs	Remove and replace with New Humidifier Tank.
Diagnosis: Initial Work Order	Diagnose and repair AC unit 1, asset #10241, issue identified
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	Includes 2.5 hours of diagnostic and 2.0 hours to install . Total 4.5 <u>HRS @ \$85.00=</u> \$382.50
Additional Material Cost to Perform Repairs	Humidifier Tank with 20% markup \$488.35
Total Cost of Repair	\$870.85



Liebert 136798P2 Image

## Liebert 136798P2 380/460/575V HUMIDIFIER BOTTLE

Part Number: Liebert-NU-136798P2

Suggested Retail: \$488.74

H-Mac Price \$375.95

28 In Stock, Orders Placed By 3pm EST Ship  
Same Day (Weekends And Holidays Excluded)

Quantity

1

Add to Cart

Ships From:

Illinois Vendor Direct

Ships By:

Free Ground, Or Choose Expedited

Weight:

2.89 (Lbs.)

Write a Review

FREE GROUND SHIPPING  
TO THE LOWER 48 STATES

CONTACT US FOR  
VOLUME DISCOUNTS



QUESTIONS

## Description