

## Additional Funding Request

<b>Site: NY058</b>	<b>WO#21488 CSS # 90368</b>
Description of Repairs	While contractor was performing work for WO 20205_CSS90368. A fourth pole light fixture has gone bad since the 11/2022 quote submitted. Will remove and replace with a new RAB LED fixture. Work is still InProgress on WO 20205. Material eta is one week. CNTR is asking for approval so this can be done as the already approved three lights are completed
Diagnosis: Initial Work Order	Troubleshoot and repair parking lot lights of training building.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	540.00
Additional Material Cost to Perform Repairs	556.00 in Matl and 750.00 for another days lift rental. Total of 1306.00
Total Cost of Repair	\$1846.00

MSL Electric, LLC

6551 GRAND AVE  
NY 11378

# Estimate

Date	Estimate #
3/8/2023	1300M

Name / Address
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

Project
NY0058 MEP CW2 Kerry P. Hein 200 NY-25A Shoreham, NY 11786

CSS
90368

Work Order

Terms

Item	Description	Qty	Rate	Total
Service	Remove one Neptune lighting fixture and replace with a new RAB LED fixture. When estimate was given 11/22/22 three heads were no longer functioning. Since November and additional head has stopped working.	4	135.00	540.00
Equipment Rental	Lift needed to reach 30 foot pole height.	1	750.00	750.00
16 Electrical & Li...	RAB Lighting Fixture, with equivalent lumens for above repair.	1	556.00	556.00

	<b>Subtotal</b>	\$1,846.00
	<b>Sales Tax (8.875%)</b>	\$0.00
	<b>Total</b>	\$1,846.00