

## Additional Funding Request

<b>Site: NY058</b>	<b>WO#21455 CSS # 92268</b>
Description of Repairs	Troubleshoot the Exit Gate. Will replace and install a new Loop detector. In the event, any further issues are detected will provide a quote for further repairs needed. This is an NTE.
Diagnosis: Initial Work Order	Troubleshoot exit gate loop. Vehicles cannot exit the facility due to the loop sensor not communicating with gate motor.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1360.00
Additional Material Cost to Perform Repairs	250.00
Total Cost of Repair	\$1610.00

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

ISG International Support Group

**ESTIMATE #** 2205

**DATE** 03/08/2023

**P.O. NUMBER**

Shoreham, NY058 Diag Exit Gate

	ACTIVITY	QTY	AMOUNT
03/08/2023	<b>Services</b> Shoreham, NY USARC NY058 Diagnose and Repair if possible Exit Gate CSS#92268	1	1,610.00

Dear Ms. DuBois:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose and repair if possible the Exit Gate at the Shoreham, NY USARC NY058 as per the following description:  
 "Troubleshoot exit gate loop.  
 Vehicles cannot exit the facility due to the loop sensor not communicating with gate motor" It is noted that problem is occurring intermittently.

Cost Breakdown:

(2) men 8 hrs @  
 \$85.....\$1,360.00  
 (1) Loop Detector  
 Module.....\$250.00

Grand  
 Total.....\$1,610.00

The cost for the above mentioned work is not to exceed \$1,610.00.

If acceptable, please do not hesitate

ACTIVITY	QTY	AMOUNT
to contact us so that we may schedule for work to be completed.		
Thank you for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		
	TOTAL	<b>\$1,610.00</b>

Accepted By

Accepted Date