

Additional Funding Request

Site: NY058	WO# 22111 CSS #93165
Description of Repairs	Repair male toilet leak (toilet will have to be removed and restored); repair male showers
Diagnosis: Initial Work Order	Multiple issue MEP Motor pool latrines
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1800.00
Additional Material Cost to Perform Repairs	170.00
Total Cost of Repair	1970.00

ACAV SERVICES

May 10, 2023



ESTIMATE 051023 CSS93165 WO22111

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW L CORBO
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	<p>NY058 MAINT SHOP</p> <p>REPAIR MALE TOILET LEAK (TOILET WILL HAVE TO BE REMOVED AND REST)</p> <p>REPAIR MALE SHOWERS</p> <p>MATERIAL</p> <p>2 EA STAINLESS STEEL SHOWER HEADS WITH STEMS</p> <p>TOILET RING SET</p> <p>TOTAL MATERIAL</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty	Item #	Description	Unit Price	Line Total
		LABOR 8 HRS @ \$225.00 PER HOUR (2 MEN 4 HRS EA)		\$1800.00
		TOTAL		\$1970.00
		THIS ESTIMATE INCLUDES THE TRAVEL TIME TO THE FACILITY AND THE TWO TRIPS WE MADE TO GAIN ENTRANCE TO EXAMINE THE PROBLEM		
TOTAL				\$1970.00

