



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd
Alexandria, VA, 22312

Sep 18, 2022

RE: Parts washer
W/O 18259
CSS# 1576

- Service Call
- Disassemble parts washer
- Install float switch
- Heating elements
- Door micro switch
- Pump motor
- Pump seal and o-rings

Unit had solvent left in it for extended period. There is significant corrosion on interior. It may be prudent for facility to price new machine. I believe they are around \$6000 new. The new parts installed will make machine function although.

Labor 16 hr x 120.00 1920.00

Parts per quote. 860.00
Shipping and handling est. 150.00

20% parts mark up. 172.00

Total Cost \$3102.00